



RADON ANALYSIS REPORT

1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

ENVIRONMENTAL TRANSACTION
35 Mill Rd
WOODCLIFF LAKE, NJ 07677

EXPOSED FOR: 01/06/2026-01/08/2026
REPORT DATE: 01/19/2026

TEST LOCATION
MANSFIELD ELEMENTARY SCHOOL
134 WARRENVILLE RD
MANSFIELD CENTER
MANSFIELD CENTER, CT 06250

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method. This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (pCi/L) OR HIGHER

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at <http://njradon.org/download/mitbas.pdf>. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. **If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office.**

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.

Jose Figueroa, RMS
NRPP CERT # 109347 RT
NRSB CERT # 18SS007

PRO-LAB NRSB # ARL0028
PRO-LAB NEHA ID # 101461AL

James E. McDonnell IV



RADON ANALYSIS REPORT

1675 North Commerce Parkway, Weston, FL 33326 (954) 384-4446

HERE ARE YOUR TEST RESULTS

<u>VIAL #</u>	<u>LOCATION</u>	<u>RADON LEVEL</u>
5570073	1ST FLOOR-MAIN OFFICE	1.3 pCi/L
5570367	1ST FLOOR-MAIN OFFICE DUP	1.3 pCi/L
5569823	1ST FLOOR-GYM FRONT	5.9 pCi/L
5569921	1ST FLOOR-GYM REAR	6.1 pCi/L
5570454	1ST FLOOR-RM 013	1.8 pCi/L
5570264	1ST FLOOR-RM 013 BLANK	< 0.3 pCi/L **
5570017	1ST FLOOR-RM 036	6.6 pCi/L
5570296	1ST FLOOR-RM 037	1.6 pCi/L
5570402	1ST FLOOR-RM 038	0.6 pCi/L
5570262	1ST FLOOR-RM 039	2.5 pCi/L
5570442	1ST FLOOR-RM 039 DUP	2.5 pCi/L
5569881	1ST FLOOR-RM 040 D	6.5 pCi/L
5570006	1ST FLOOR-RM 146 A	1.1 pCi/L
5570136	1ST FLOOR-RM 146 B	1.6 pCi/L
5569638	1ST FLOOR-RM 146 C	1.4 pCi/L
5570137	1ST FLOOR-RM 146 G	1.2 pCi/L
5570042	1ST FLOOR-RM 35	3.6 pCi/L
5570460	1ST FLOOR-RM 36	2.8 pCi/L
5570475	1ST FLOOR-STAGE	6.3 pCi/L